

Step and Gap Gauge


Series 437






Features

Measure step height and gap width Resolution: 0.01mm/0.0005" Buttons: on/off, zero, mm/inch Automatic power on/off Data output(cable code:100-11 or 100-12) Made of stainless steel Supplied with zero setting block





Specifications

Part No	Range	Accuracy
AC-437-001-11	0-12.7mm/0-0.5"	±0.03mm

